

LH

ENGINE LOG



REG. NO.	N4137J	Ron's Aircraft Service, Inc. 2810 PERIMETER RD., STE. 101 NORTH LAS VEGAS, NV 89030 FAA CRS NO. RJUR641K Engine Logbook Entry	DATE	11/22/99
MODEL	PA-34-220T		W.O. #	9839
S/N	3449085		HOBBS	592.0
ENG. MOD.	TSIO-360-RB1B		TACH	
ENG. S/N	321475		TOTAL TIME	592.0
POSITION	Left		TSO	

Changed oil and filter inspected oil filter element. Serviced engine with Aeroshell 15W50. Compression checks 1 72/80, 2 70/80, 3 70/80, 4 72/80, 5 72/80, 6 68/80. Cleaned, gapped and rotated spark plugs. Checked magnetos per requirements outlined in inspection checklist. Replaced oil cooler gasket. Engine inspected as part of an Annual inspection and was found in airworthy condition. Ground ops and leak checked okay.

SIGNED Ronald K Beard

Date: 12/06/99 Tach: 644.7 W/O 9918

Changed oil and filter inspected oil filter element. Serviced engine with Aeroshell 15W50. Complied with TCM SB 98-8 modified #1 and 3 cylinder intake tubes. Ground ops and leak checked okay.

Ron's Aircraft Service, Inc. FAA RS #RJUR641K, Ronald K Beard

Total To Carry Forward			
------------------------	--	--	--

and Remarks	Signature	Certificate No.
5/22/00 Hobbs: 870.2	Eagle East Aviation Inc. Lawrence Municipal Arpt North Andover MA 01845	N4137J Left Engine
Drained oil and removed filter. Cut and insp filter. No contamination found at this time. Installed new filter and serviced with 8 qts Aeroshell 15/50. Cleaned fuel injector nozzles and reinstalled with new o-rings. Replaced all 12 spark plugs Ran up and leak checked all functions proved to be satisfactory at this time	<u>Ross A Desmet</u>	
	Ross A Desmet AP 32509932	
7/27/00 Hobbs: 920.4	Eagle East Aviation, Inc. Lawrence Municipal Arpt North Andover MA 01845	N4137J
Replaced Left Engine magnetos, both left and right. Right magneto, Slick model # 6324, serial number 00061050. Left magneto, Slick model # 6324, serial number 99120330. Ops check ok.	<u>Rob Harring</u>	
	Rob Harring A/P 28520433	

